



Photo 1. 12-22-10 GH Dairy #1. View looking east from Grove Avenue. Spillway is in west berm along Grove Avenue. Discharge flows south (left to right) on Grove.



View looking south on Grove Avenue for reference to Photo 1. (Google Earth Street View)



Photo 2. 12-22-10 GH Dairy #1. View looking north from Merrill Avenue. View of south berm along Merrill Avenue. Discharge from rodent hole. Discharge flows west (right to left) on Merrill



View looking east on Merrill Avenue for reference to Photo 2. (Google Earth Street View)



Photo 2. 12-22-10 GH Dairy #1. View looking west from Merrill Avenue. View of south berm along Merrill Avenue. Discharge from rodent hole. Discharge flows west (lower center to upper left) on Merrill



View looking west on Merrill Avenue for reference to Photo 3. (Google Earth Street View)



Photo 2. 12-22-10 GH Dairy #1. View looking west from Merrill Avenue. View of south berm along Merrill Avenue. Discharge from rodent hole. Discharge flows west (lower left to top) on Merrill



View looking west on Merrill Avenue for reference to Photo 4. (Google Earth Street View)



GH Dairy #1. Google Earth satellite imagery with discharge locations.